SF82 ONLINE DEW-POINT HYGROMETER

A panel or bench mount fast response hygrometer with digital display, analog and digital Modbus RTU outputs and dual alarm feature, offering excellent reliability and repeatability.

Feature {A} B Feature {B} T Feature {C} R Feature {D} P	Item Base Model SF82-OL-HYG Type B1 B2 B3 Range C1	Description SF82 Online Hygrometer (2-wire, 1/8 DIN panel mount, 2 alarms, sampling block) G1/2" BSP Process Connection 3/4" UNF Process Connection 5/8" UNF Process Connection	
Feature {B} T	SF82-OL-HYG Type B1 B2 B3 Range C1	G1/2" BSP Process Connection 3/4" UNF Process Connection 5/8" UNF Process Connection	
Feature {C} R	B1 B2 B3 Range C1	G1/2" BSP Process Connection 3/4" UNF Process Connection 5/8" UNF Process Connection	
Feature {C} R	B1 B2 B3 Range C1	3/4" UNF Process Connection 5/8" UNF Process Connection	
Feature {D}	B2 B3 Range C1	3/4" UNF Process Connection 5/8" UNF Process Connection	
Feature {D}	B3 Range C1	5/8" UNF Process Connection	
Feature {D}	Range C1		
Feature {D}	C1		
		60/ 60001	
		-60/+60°Cdp output scaled 4-20mA range	
	C2	-50/+50°Cdp output scaled 4-20mA range	
	C3	-50/+30°Cdp output scaled 4-20mA range	
Feature {E} E	Protection		
Feature {E}	D1	Standard HMWPE guard (for protection against fine particulates (<10 µm))	
	Electrical Connector		
	E1	MiniDIN 43650 C	
	E2	M12 5 Pin	
Feature {F}	Power		
	F1	85 to 265 V AC	
Feature {G}	Cable		
	G1	M12 Sensor Cable 0.8m	
	G2	M12 Sensor Cable 2m	
	G3	M12 Sensor Cable 5m	
	G4	M12 Sensor Cable 10m	
	G5	MiniDIN Sensor Cable 0.8m	
	G6	MiniDIN Sensor Cable 2m	
	G7	MiniDIN Sensor Cable 5m	
	G8	MiniDIN Sensor Cable 10m	

Ordering Example

SF82-OL-	SF82 Online, -60 to +60°C dp range, HMWPE guard, 85 to 265 V AC power supply & 0.8m (2.62') cable with
HYG+B3+C1+D1+E2+F1+G5	M12 connector

SF82 ONLINE DEW-POINT HYGROMETER ACCESSORIES AND SPARE PARTS

Product Parent Code: SF82-TX SF82 Transmitter 2-Wire 4-20mA Output			
Product Orde	roduct Ordering Code {Feature A}+{Feature B}+{Feature C}+{Feature D}+{Feature E}		
Feature	Item	Description	
Feature {A}			
	SF82-TX	A rugged dew-point transmitter for continuous measurement in industrial dryer applications	
Feature {B}	Туре		
	B1	G1/2" BSP Process Connection	
	B2	3/4" UNF Process Connection	
	В3	5/8" UNF Process Connection	
Feature {C}* Range			
	C1	-60/+60°Cdp output scaled 4-20mA range	
	C2	-50/+50°Cdp output scaled 4-20mA range	
	C3	-50/+30°Cdp output scaled 4-20mA range	
Feature {D}	Protection		
	D1	Standard HMWPE guard (for protection against fine particulates (<10 µm))	
Feature {E}	ure {E} Electrical Connector		
	E1	MiniDIN 43650 C	
	** E2	M12 5 Pin	

* - Non-standard scaled ranges available upon request - refer to Peter Shepherd
** - Selection of M12 5 pin connector version enables the SF82 to output 4 to 20 mA and Modbus RTU over RS485 outputs
*** - M12 5 Pin connector is not supplied with the product and should be ordered separately from the accessories list

Ordering Example

SF82-TX+B1+C1+D1+E1	SF82 Transmitter, 2-wire, 4-20mA output, G 1/2" BSP, measurement range -60 to +60°Cdp, HMWPE guard, MiniDin 43650 C
---------------------	---

Order Codes	Product / Description	Proc	ess Connec	tion
		G1/2" BSP	3/4 " UNF	5/8 " UNF
Spares	1	1		ī
SF82-HMP	Pack of 10 replacement HMWPE guards (for protection against fine particulates <10µm)	✓	✓	✓
GEN-LABEL	Additional/replacement transmitter labels (price per 2 off labels)	✓	✓	✓
BS-12-PK5	5/8" UNF Bonded Seal for process connection (pack of 5)	✓		
OR-34-PK5	G1/2" Bonded Seal for process connection (pack of 5)		✓	
BS-58-PK5	3/4" UNF Viton O-ring for process connection (pack of 5)			✓
EA2-SC	MiniDIN sensor connector socket	✓	✓	✓
EA2-SCG	Sensor Connector MiniDIN Gasket	✓	✓	✓
Sampling Accessories				•
APT-PAN	5/8" UNF (Internal) to 3/4" UNF (External) Adapter Collar			✓
APT-GEI	5/8" UNF (Internal) to G1/2" (External) Adapter Collar			✓
APT-TSO	5/8" UNF (Internal) to 1/2" NPT (External) Adapter Collar			✓
SB-12	G1/2" SS sample block (with 1/8" NPT inlet & outlet ports)	✓		
SB34-SF82	SS 3/4" sample block (with 1/8" BSP and 1/4" BSP ports)		✓	
SB-12-QF	G 1/2" Quick Fit Sample Block with DN7.2 Quick Connector for compressed air. Outlet vent to atmosphere	√		
SB-58-QF	5/8" UNF Quick Fit Sample Block with DN7.2 Quick Connector for compressed air. Outlet vent to atmosphere			✓
APT-KF40-34	KF40 Adaptor Flange for ¾ UNF Sensors		✓	
APT-KF40-58	KF40 Adaptor Flange for 5/8 UNF Sensors			✓
CSB	5/8" UNF SS sample block (with 1/8" NPT inlet & outlet ports)			✓
EA2-SAM	5/8" UNF Sampler Kit (for atmospheric or pressure dp measurements, 145 psig/10 barg max)			✓
EA2-SAM-HP	5/8" UNF HP (High Pressure) Sampler Kit - (for atmospheric or pressure dp measurements, 2900 psig/200 barg max)			✓
PTFE-xx	PTFE sample tube 6mm (0.24") O/D thick-walled (for Sampler Kit) $(xx = length \ of \ tube \ in \ meters - price \ per \ meter- \ above 0.5m)$	1		✓
Electrical Accessories	•	•		
EA2-OL-MON-29739	RS485 Serial Comms Cable for Online monitor	✓	✓	✓
EA2-CAB-0.8	Cable, 0.8m (2.62') length with mini-DIN mating socket	✓	✓	✓
EA2-CAB-02	Cable, 2m (6.56') length with mini-DIN mating socket	✓	✓	✓
EA2-CAB-05	Cable, 5m (16.4') length with mini-DIN mating socket	✓	✓	✓
EA2-CAB-10	Cable, 10m (32.8') length with mini-DIN mating socket	✓	✓	✓
EA2-M12-CAB-0.8	Sensor Cable, 0.8m (2.62') with M12 Sensor Connector	✓	✓	✓
EA2-M12-CAB-02	Sensor Cable, 2m (6.56') with M12 Sensor Connector	✓	✓	✓
EA2-M12-CAB-05	Sensor Cable, 5m (16.4') with M12 Sensor Connector	✓	✓	✓
EA2-M12-CAB-10	Sensor Cable, 10m (32.8') with M12 Sensor Connector	✓	✓	✓
	Other cable lengths available upon request	•		•

SF82 ONLINE DEW-POINT TRANSMITTER ACCESSORIES AND SPARE PARTS

31 02 OI	SI 02 OILLINE DEW-FOINT TRANSMITTER ACCESSORIES AND SPARE PARTS			
Order Codes		Product / Description		
Product Orde	Product Ordering Code {Feature A}+{Feature B}			
Feature {A}	Base Model			
	EAU-CK	Easidew, SF82 & Pura Universal Comms Kit		
Feature {B}	ure {B} Cable			
	B1	EA2 MiniDIN Connector 0.5m sensor lead		
	B2	EA PRO IS & EA PRO XP Terminal Block Connector 0.5m sensor lead		
	В3	EA2 5 Way M12 Connector 0.5m sensor lead (not suitable for SF72 Rail M12 4 pin)		

EAU-CK ACCESSORIES AND SPARE PARTS

EAU-CK-CAB1	Spare EA2 MiniDIN Connector 0.5m sensor lead
EAU-CK-CAB2	Spare EA PRO IS & EA PRO XP Terminal Block Connector 0.5m sensor lead
EAU-CK-CAB3	Spare EA2 5 Way M12 Connector 0.5m sensor lead (not suitable for SF72 Rail M12 4 pin)

SF82 ONLINE DEW-POINT TRANSMITTER SERVICE EXCHANGE

31 02 01	ILLIAL DE VV	-POINT TRANSMITTER SERVICE EXCHANGE
Order Codes		Product / Description
Product Ordering Code {Feature A}+{Feature B}+{Feature C}		
Feature (A)	Base Model	
	SF82-TX-X	Base unit
Feature {B}	Туре	
	B1	G1/2" BSP Process Connection
	B2	3/4" UNF Process Connection
	В3	5/8" UNF Process Connection
Feature {C}*	Range	
	C1	-60/+60°Cdp output scaled 4-20mA range
	C2	-50/+50°Cdp output scaled 4-20mA range
	C3	-50/+30°Cdp output scaled 4-20mA range
		Non-standard measurement range:
		v = zero value, w = full scale value,
		$x = unit (C = {}^{\circ}Cdp, F = {}^{\circ}Fdp, P = ppmV)$
	(v/wx-yz)	y = Pressure for ppmV conversion in bar/psi,
		z = pressure unit (PG=psig, PA=psia, BG=barg, BA=bara) blank = 0 barg/psig)
		e.g. 0-100ppm @ 10barg = 0/100P-10BG
Feature {D}	Protection	
	D1	Standard HMWPE guard (for protection against fine particulates (<10 µm))
Feature {E}	Electrical Connec	ctor
	E1	MiniDIN 43650 C
	** E2	M12 5 Pin

* - Non-standard scaled ranges available upon request - refer to Peter Shepherd
** - Selection of M12 5 pin connector version enables the SF82 to output 4 to 20 mA and Modbus RTU over RS485 outputs
*** - M12 5 Pin connector is not supplied with the product and should be ordered separately from the accessories list

SF82 CALIBRATION SERVICES

SF82-TX-Recal	Recalibration of SF82 Transmitter (Supplied with traceable calibration certificate)
READINGS-DPS	Readings before calibration (calibration data recorded before adjustment) - Dew-Point Sensors

Please note: Michell Instruments adopts a continuous development program which sometimes necessitates specification changes without notice. Please contact us for latest version. Issue No: SF82 Online_97167_V3 UK_1121